

Peoria Lake 2000 Site Visit





RICHARD E. BROOKS

FOREST WETLAND MGT. AREA

Along cross levee looking towards ILWW.



Spill way with stop log structures.



Demonstrating stop log removal.




Channel along cross dike leading to ILWW.



Levee between two of the ponding areas.



Levee between the river and outer ponding area.
Note overtopped area where gravel ends.



Grass intrusion into ecosystem



Levee between river and outer cell.
Gravel ends at previously eroded section.



Levee between river and outer cell (area without gravel).





A photograph of a wooded area with bare trees and a body of water in the background. The foreground is filled with dry, brown grass and fallen branches. The trees are mostly without leaves, showing their intricate branch structures. In the background, a calm body of water reflects the overcast sky. The overall tone is muted and wintry.

Historic well near river.



View of the Islands.


Duck Blind



Islands

Three Sisters Park.

Waterfowl.



Downstream end of Islands.

Islands.





Road towards the spill ways.



Mast Tree planting



Mast Tree planting



Mast Tree planting.